

From: Shyam Sunder <sunder@nist.gov>  
To: "'wtc@nist.gov'" <wtc@nist.gov>  
Subject: FW: Dr Sunder

---

Dr. S. Shyam Sunder  
Director  
Building and Fire Research Laboratory  
National Institute of Standards and Technology  
Gaithersburg, MD 20899-8600  
Tel.: 301-975-5900; Fax: 301-975-4032

---

---

**From:** Betty Crawford [mailto:BettyCrawford1@sbcglobal.net]  
**Sent:** Monday, August 25, 2008 1:07 PM  
**To:** Shyam Sunder  
**Subject:** Dr Sunder

I'm praying that you take the peer reviewed research from Dr Steven Jones/ Kevin Ryan concerning the collapse of WTC Building 7 and complete your WTC research. What your proposing is ridiculous. Your saying fire and expansion of load bearing beams brought down WTC 7 symmetrically. You say that load bearing column 79 (on the wide side of a trapezoidal shaped building) was the initiate to collapse. If that were the case then how did the building fall symmetrically as this column

was on the wide(heavier) part of this structure. Common sense/physics dictates that if this were the case the building should have fallen over toward the collapsed beam side..common senseical. Further FEMA admitted years ago that even if the diesel had exploded in the storage tanks in the basement it had a low probability of causing catastrophic collapse. Now your saying that fire was the culprit????????? Your reasoning that molten metal in the basements of WTC 1, 2 and 7 from dieselcarbon fuel based fire (buried in a basement by tons of debris) is ridiculous. Where is this superheated fire supposed to get its oxygen from?????? Open air foundries have to have a tremendous air/oxygen source or the fire will never get hot enough to create molten metal to pour. Of course your an expert and already know this I assume. From this I can only conclude that you know better...Please explain?

Sincerely  
Dr Keith Crawford  
ae911truth.org